

vw.runnionequipment.com

EOUIPMENT

Boom Trucks – Stand Up, Swing Cab, Tractor Mounted

Telescoping

Knuckleboom, Articulated

Material Handling, Log Loader

Truck Mounted

Pedestal Mounted

Rolling Base

Trailer Mount

Marine Mount

Bucket Trucks

Sign Cranes

Trailers – Tag, Sliding Axle, Hydraulic Tail, Lowboy, Blade, Schnabel, Custom

Crane Attachments – Forks, Buckets, Roofing Boxes, Line Blocks

Aftermarket Accessories – Custom Straps, Slings, Safety Gear

Hy Rail Railroad Gear

SERVICES

Technical on-site field service by factory trained technicians

Product and parts support

OSHA Inspections

Operator safety training seminars

Preventive maintenance programs

Rail gear inspections and maintenance

Rental Equipment

Used Equipment

Consignments

Custom hydraulic hoses

Financing assistance

LOCATIONS

Illinois

Corporate Headquarters 7950 47th St. Lyons, IL 60534 Phone: 800-824-6704

Fax: 708-447-3730

Wisconsin

Sales & Rentals 1021 A S. 27th St. Caledonia, WI 53108 Phone: 262-703-4463

Service

N60 W14752 Kaul Ave. Menomonee Falls, WI 53051 Phone: 262-703-4463

www.runnionequipment.com

NATIONAL CRANE

How to Avoid

the Most Common OSHA Crane Violations

Training and Documentation

1926.1428(a)—The signal person has not been qualified through a third party evaluator or the employer's qualified evaluator.

1926.1425©(3)—Materials were not rigged by a qualified rigger.

926.1428(a)(3))—No documentation was available for the signal person.

Runnion Equipment offers training and qualifying examinations for signal persons and riggers at our locations.



Annual Inspections

1926.1412(f)(1)—Annual inspections had not been performed by a qualified person

1926.1411(f)(2)(xvii)—Labels supplied by the manufacturer were missing.

Runnion Equipment provides flat rate OSHA inspections to assure your cranes comply with regulations, including displaying all required labels.



20 Foot Radius from Power Lines

926.1408(a)(2)—No determination had been made to ensure the working radius was within 20 feet of a power line.

Establish a work zone with flags or use high voltage proximity alarms to maintain a 20-foot distance from power lines. Both are available from Runnion Equipment.



Record Maintenance

1926.1417©(1)—The operator's manual, load charts, hazard warnings, etc. are not in the cab at all times.

1926.1412(e)(3)(i)—Monthly crane inspection results are missing and/or signed documentation is not maintained.

Maintain documentation of shift, monthly, and annual inspections for at least three months. Documentation must include the items checked and the results of the inspection, as well as the name and signature of the person who conducted the inspection and the date of each inspection. Runnion Equipment provides proper documentation of any inspections conducted.



Correction of Deficiencies

1926.1412(d)(1)—A safety determination was not made by a competent person after a deficiency had been noted during an inspection.

When the qualified person who conducts the inspection identifies any deficiency during the inspection that constitutes a safety hazard, the equipment must be taken out of service until the deficiency is corrected. To get your crane operational quickly, Runnion Equipment provides emergency on-site service.



For training, inspections and quick service, call us today!